



FIRING SCHEDULE FOR SKUTT KM ELECTRONIC KILNS SLUMP/FORMING

RA 1 300° /HR TO 900° , HOLD 30 MINUTES, NO ALARM

RA 2 500° /HR TO 1250° , HOLD 30 MINUTES, NO ALARM

RA 3 9999° /HR TO 1025° , HOLD 30 MINUTES, NO ALARM

RA 4 60° /HR TO 700° , NO HOLD, NO ALARM